


NPS56-79-006



NAVAL POSTGRADUATE SCHOOL Monterey, California





COMBAT DAMAGE ASSESSMENT TEAM A-10/GAU-8 LOW ANGLE FIRINGS **VERSUS** SIMULATED SOVIET TANK COMPANY (15 June 1978)

R.H.S. Stolfi

J.E. Clemens

R.R. McEachin

August 1979

Approved for public release; distribution unlimited.

Prepared for: A-10 System Program Office

Wright Patterson Air Force Base Ohio 45433

S

ND A 0 761

79 11 -02 001

NAVAL POSTGRADUATE SCHOOL Monterey, California

Rear Admiral Tyler F. Dedman Superintendent

Jack R. Borsting Provost

The work reported herein was supported by the A-10 System Program Office, Wright Patterson Air Force Base, Ohio. The reproduction of all or part of this report is authorized.

Russel H.S. Stolfi

Associate Professor of History

Reviewed by:

Edward J. Vlaurance

Edward J.NLaurance Assoc. Chairman

Department of National Security Affairs Released by:

W.M. Tolles Dean of Research

9 Special repte,

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM
	3. RECIPIENT'S CATALOG NUMBER
NPS56-79-006	5. TYPE OF REPORT & PERIOD COVERED
A. TITLE (and Substitle) Combat Damage Assessment Team, A-10/GAU-8	Special Penant for Arra
Low Angle Firings Versus Simulated Soviet	Firings of 15 June 1978
Tank Company (15 June 1978)	6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(e)	B. CONTRACT OR GRANT NUMBER(*)
R.H.S. Stolfi J.E. Clemens R.R. McEachin	None (12)89/
9: PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK
Naval Postgraduate School Monterey, California 93940 MIPR-	F 47615-78-5209 and FY -7621-78-90220
11. CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE
A-10 System Program Office Wright Patterson Air Force Base	August 1979
Ohio 45433	
14. MONITORING AGENCY NAME & ADDRESS(If different from Controlling Office)	15. SECURITY CLASS. (of this report)
	Unclassified
	15. DECLASSIFICATION/DOWNGRADING
16. DISTRIBUTION STATEMENT (of this Report)	SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution	
	unlimited .
Approved for public release; distribution	unlimited .
Approved for public release; distribution 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different from 18. SUPPLEMENTARY NOTES The first in a two volume see	unlimited om Report)
Approved for public release; distribution 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from 18. SUPPLEMENTARY NOTES The first in a two volume set of the province of the first in a two volume set of the first in a two volumes.	unlimited on Report)
Approved for public release; distribution 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from 18. SUPPLEMENTARY NOTES The first in a two volume sets the set work of the sets of	unlimited om Report)
Approved for public release; distribution 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from 18. SUPPLEMENTARY NOTES The first in a two volume set of the automatic cannon ammunition 5. empi 2. GAU-8 cannon 3. A-10 aircraft 7. gun	unlimited om Report) rical tests at stowed targets ammunition lethality
Approved for public release; distribution 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from 18. SUPPLEMENTARY NOTES The first in a two volume set of the second se	unlimited om Report) rical tests at stowed targets ammunition lethality vulnerability and
Approved for public release; distribution 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from 18. SUPPLEMENTARY NOTES The first in a two volume set of the entered in Block 20, If different from 1. automatic cannon ammunition 5. empi 2. GAU-8 cannon 6. comb 3. A-10 aircraft 7. gun 4. main battle tank (MBT) 8. MBT surv	unlimited om Report) rical tests at stowed targets ammunition lethality vulnerability and ivability
Approved for public release; distribution 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different for 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse elde if necessary and identify by block number 1. automatic cannon ammunition 5. empi 2. GAU-8 cannon 6. comb 3. A-10 aircraft 7. gun 4. main battle tank (MBT) 8. MBT SURV 20. ABSTRACT (Continue on reverse elde if necessary and identify by block number) This report, describes firings of the on 15 June 1978, against a Soviet tank co combat loaded M-47 tanks. The pilots mak attacked at low altitude and correspondin	unlimited on Report) rical tests at stowed targets ammunition lethality vulnerability and ivability A-10/GAU-8 weapon syste mpany simulated by ten ing the firing passes g low dive angles simu-
Approved for public release; distribution 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, II different from 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side II necessary and Identity by block number) 1. automatic cannon ammunition 5. empi 2. GAU-8 cannon 6. comb 3. A-10 aircraft 7. gun 4. main battle tank (MBT) 8. MBT surv 20. ABSTRACT (Continue on reverse side II necessary and Identity by block number) This report, describes firings of the on 15 June 1978, against a Soviet tank co combat loaded M-47 tanks. The pilots mak attacked at low altitude and correspondin lating movement through a hostile air def tion used in the attacks comprised 30mm a	unlimited on Report) rical tests at stowed targets ammunition lethality vulnerability and ivability A-10/GAU-8 weapon syste mpany simulated by ten ing the firing passes g low dive angles simu- ense system. Ammuni- rmor piercing incendiary
Approved for public release; distribution 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, 11 different from 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side if necessary and identify by block number) 1. automatic cannon ammunition 5. empi 2. GAU-8 cannon 6. comb 3. A-10 aircraft 7. gun 4. main battle tank (MBT) 8. MBT SURV 20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report, describes firings of the on 15 June 1978, against a Soviet tank co combat loaded M-47 tanks. The pilots mak attacked at low altitude and correspondin lating movement through a hostile air def	unlimited on Report) rical tests at stowed targets ammunition lethality vulnerability and ivability A-10/GAU-8 weapon system mpany simulated by ten ing the firing passes g low dive angles simu- ense system. Ammuni- rmor piercing incendiary

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE S/N 0102-014-6601 |

UNCLASSIFIED

pover)

LECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

pilots in 23 firing passes achieved 347 impacts on the ten target tanks. The impacts included 50 perforations of the armored envelopes and resulted in damage comprising six tanks catastrophically killed, three tanks incapable of fire and movement, and one tank with degraded mobility.

4

TABLE OF CONTENTS

Volume and Subject	Page
Volume 1	
Combat Damage Assessment Committee (CDAC),	
Executive Summary of the A-10/GAU-8 Low Angle	
Firings Versus Simulated Soviet Tank Company,	
15 June 1978	1
Appendix A: Combat Damage Assessment	-
Committee (CDAC), Report on the A-10/GAU-8	
Low Angle Firings Versus Simulated Soviet	
Tank Company, 15 June 1978	
I. Background	A-1
II. Test Philosophy	A-2
III. The Simulated Ground Combat Situation	A-2
IV. The Target Tanks	
V. The Test and Results	A-4
VI. Combat Damage Assessment	A-7
VII. Summary and Conclusions	A-32
Volume 2 (Issued Under Separate Cover)	A-67
Tost Possistion and Analysis Cover)	
Test Description and Analysis Group,	
Results of the A-10A Combat Lethality Assessment	
Test of 15 June 1978.	

NTIS	White Section
DDC	Buff Section
UNANNOUNCED	
JUSTIFICATION	
	VAILABILITY CODES
	and/or SPECIAL

LIST OF ILLUSTRATIONS

Illustratio	ons Pag	<u>je</u>
Table I	TWO A-10 AIRCRAFT IN LOW ANGLE GUN ATTACK VS SIMULATED SOVIET TANK COMPANY	5
Table II		-18
Table III	TEST RESULTS: AIRCRAFT ATTACK	10
Table 111		-19
Table IV	THE RESULTS: AIRCRAFT ATTACK	-12
Table IV		-20
Table V	THE RESULTS: AIRCRAFT ATTACK BURST LENGTHS	-20
IdDIE A		-25
Table VI	GUN EFFECTS: IMPACT CHARACTERISTICS	-25
Table VI		20
Mahla WIT		-26
Table VII		-27
Table VIII	TANK DAMAGE: OVERALL PICTURE; KM, M,	20
mahla TV		-28
Table IX	TANK DAMAGE, LOCATIONS OF PERFORATIONS A	-29
Figure 1	EMPIRICAL TEST PHILOSOPHY A	-3
Figure 2	THE TANK TARGET ARRAYA	-5
Figure 3	THE PROJECTILE: 30mm API FOR GAU-8 GUN A	
Figure 4		
Figure 5	THE GUN: GAU-8 30mm GATLING A THE AIRCRAFT: USAF A-10 A	_12
Figure 6	THE TARGET: M-47 COMBAT TANK A	_12
Figure 7	TRANSCRIPT OF PILOTS' IN-FLIGHT VOICE	_13
rigure /	RECORDING, BATTLEFIELD OBSCURATION	
		-21
Figure 8	AIRCRAFT VERTICAL FLIGHT PATH, 15 JUN 79,	-21
rigure o		-22
Figure 9	AIRCRAFT VERTICAL FLIGHT PATH, 15 JUN 79,	-22
		-23
	AIRCRAFT VERTICAL FLIGHT PATH, 15 JUN 79,	-2.5
rigure 10		-24
Figure 11	A-10/GAU-8 MEASURES OF EFFECTIVENESS	-24
rigure ii		-30
Figure 12	A-10/GAU-8 VERSUS SIMULATED SOVIET TANK	-30
riguic iz		-31
Figure 13		-35
Figure 14		-35
Figure 15		-35 -36
Figure 16		
Figure 17		-36
		-38
Figure 18		-38
Figure 19		-39
Figure 20		-39
Figure 21	TARGET 4, IMPACTS 28 AND 29A-	-40
Figure 22	TARGET 5, INTERIOR VIEW OF IMPACTS 5 AND 6 A	
Biomes 22		-42
		-42
ridure 24	TARGET D. IMPACT II 1	-43

Illustr	cation	ns														Page
Figure	25	TARGET	5,	INTERI	OR	VIE	W	OF	IMP.	ACT	11	_	_	-	_	A-43
Figure	26	TARGET	6,	IMPACT	3	-	-					-	_	-	-	A-45
Figure	27	TARGET	6,	IMPACT	10	-	-		-			-	-	-	-	A-45
Figure	28	TARGET	6,	IMPACT	33	-	-		-			-	-	-	-	A-46
Figure	29	TARGET	7,	IMPACT	1	-	-		-			-	-	-	-	A-48
Figure	30	TARGET	7,	IMPACT	9	-	-		-			-	-	-	-	A-49
Figure	31	TARGET	7,	IMPACT	10	-	-					-	-	-	-	A-49
Figure	32	TARGET	11,	IMPAC'	r 3	-	-					-	-	-	-	A-51
Figure	33	TARGET	11,	INTER	IOR	VI	EW	OF	IM	PACT	4-	-	-	-	-	A-51
Figure	34	TARGET	11,	IMPAC'	r 1	2-	-					-	-	-	-	A-52
Figure	35	TARGET	11,	IMPAC'	r 1	3-	-					-	-	-	-	A-52
Figure	36	TARGET	11,		_	8-	-					-	-	-	-	A-53
Figure		TARGET	11,	IMPAC'	Г 2	3-	-					-	-	-	-	A-53
Figure	38	TARGET	11,	IMPAC'	r 2	7-	-					-	-	-	-	A-54
Figure	39	TARGET	12,	IMPAC'	r 7	-	-					-	-	-	-	A-56
Figure		TARGET	12,				-					-	-	-	-	A-56
Figure	41	TARGET	12,	IMPAC'	Г 2	0-	-					-	-	-	-	A-57
Figure		TARGET	14,	IMPAC'	r 1	3-	-					-	-	-	-	A-59
Figure	43	TARGET	14,	INTER	IOR	VI	EW	OF	IM	PACT	13	-	-	-	-	A-60
Figure		TARGET	15,		rs	2 A	ND	3				-	-	-	-	A-62
Figure	45	TARGET	16,				-					-	-	-	-	A-64
Figure		TARGET	16,	INTER	IOR	VI	EW	OF	IM	PACT	8-	-	-	-	-	A - 64
Figure		TARGET	16,				-		-			-	-	-	-	A-65
Figure			16,								12	-	-	-	-	A-65
Figure		TARGET	16,										-	-	-	A-66
Figure	50		16,		rs	17,	1	8,	19,	20	21	,				
		22, 23,	AN	D 24-		-	-					-	-	-	-	A-66
Sketch	1	THE US	M-4	7 TANK	: Т	URF	ET	ov	ERH	ANG						
		AND 180		REAR)							TTY	_	-	_	_	A-6

COMBAT DAMAGE ASSESSMENT TEAM

A-10/GAU-8 LOW ANGLE FIRINGS

versus

SIMULATED SOVIET TANK COMPANY (15 June 1978)

EXECUTIVE SUMMARY

DR. R.H.S. STOLFI, Naval Postgraduate School

MR. J.E. CLEMENS, Battelle Columbus

MR. R.R. McEACHIN, Battelle Columbus

EXECUTIVE SUMMARY

Under the technical direction of the Combat Damage Assessment Team (CDAT) ment Committee (CDAC), the Combat Damage Assessment Team (CDAT) conducted firings of the A-10/GAU-8 weapon system against an array of 10 tanks simulating a Soviet tank company deployed for an attack. The CDAT used M-47 tanks stowed with main gun ammunition, diesel fuel, lubricating oil, and crew mannikins to simulate the Soviet tanks. The pilots of the two A-10 aircraft used in the firings conducted their firings at low altitudes and low dive angles which simulated attack below the altitude of effective engagement for opposing air defense networks employing acquisition and fire control radar. The purpose of the test was to evaluate the effects of the 30mm API antitank ammunition of the GAU-8 gun under challenging conditions of engagement for the A-10/GAU-8 system against realistically simulated Soviet tank formations.

The Combat Damage Assessment Committee assessed the results of the low angle cannon firings of the two A-10 aircraft against the simulated Soviet tank company as follows:

1. Attack Parameters: The pilots of the A-10 aircraft attacked the simulated Soviet tank company for 10 minutes 30 seconds at low altitude and dive angles. The pilots made a total of 23 passes each at a primary tank target. The passes resulted in projectile impacts on 23 primary, ten secondary, and 5 incidental target tanks, i.e., the pilots impacted every primary tar-

get and in addition inflicted damage 18 times each on secondary and incidental tank targets near the primary. The attack open fire dive angles averaged 7.1° during 23 passes against the targets. Open fire slant ranges averaged 2759 feet and cease fire slant ranges 2078 feet. The pilots fired 1969 rounds in 23 bursts averaging 86 rounds and 1.3 seconds each.

- 2. Weapon Effects: The A-10/GAU-8 weapon system achieved 347 impacts on the ten tank targets. The ratio of impacts to total rounds fired was a substantial 0.18. The weapons system achieved 50 perforations of the armored envelopes of the tanks with a ratio of perforations to impacts of 0.14. Many projectiles, which did not perforate armor, severely damaged exterior track and suspension components of the tanks as well as command and control optical devices and gun tubes.
- 3. <u>Damage Assessment</u>: The attacking A-10/GAU-8 weapon systems inflicted six catastrophic kills on tanks in the company array. Three additional tanks in the array did not explode or burn but were severely damaged within the time frame of the aerial attack and rendered incapable of both fire and movement. One final tank in the array suffered only moderate damage; it remained capable of firing but was reduced in its ability to maneuver. As a formation, the simulated Soviet tank company was for any practical purpose destroyed.
- 4. Test Conditions: The target tanks were sited in open, flat desert terrain with no cover and little concealment. Aerial weather conditions were ones of unlimited ceiling and visibility.

Shortly after the initial firing passes black smoke from burning and exploding tanks and clouds of white dust from projectile impacts were evident. Such conditions effectively simulated the actual obscuration which would have been presented to the pilots in combat and reduced their effectiveness in several firing passes as evidenced by in-flight voice recordings of the mission.

- 5. <u>Summary and Conclusions</u>: Under contrasting firing conditions of ideal weather and open, flat terrain but challenging low altitude attack parameters and battlefield smoke and dust obscuration, the A-10/GAU-8 weapon system knocked out nine of ten tanks in the simulated Soviet tank company. The term, knocked out, comprises the following conditions: six tanks suffered internal explosions and fires and three additional tanks were immobilized and simultaneously rendered incapable of firing their main armament. The observed and documented results support the conclusion that:
- a. The A-10/GAU-8 weapon system employing 30mm API projectiles has the accuracy and lethality to destroy M-47 and similarly protected tanks, e.g., Soviet T-55 and T-62 tanks, under realistic firing conditions.
- b. GAU-8 30mm API projectiles fired in realistic low level passes by A-10 aircraft can perforate the sides and rear of main battle tanks and cause catastrophic damage through explosion of tank ammunition and ignition of fuel and oil.
- c. GAU-8 30mm API projectiles which do not perforate the armor of main battle tanks have the capability to immobilize them through damage to exterior track, suspension, and drive components.

- d. From the viewpoint of GAU-8 30mm API ammunition effects and resulting damage to combat stowed main battle tanks, the tactic of low level attack was shown in this firing test to be a successful one.
- 6. The overall results of the test are summarized in the accompanying Table I.

TABLE I.

	TANK	ASPECT			RT SIDE			RT SIDE		RT SIDE			RT SIDE		RT SIDE			RT SIDE				RT SIDE	RT SIDE		RT SIDE	
Y		TANK	IMMOB		100			100		100			100		100			100			-	100	100		,	
COMPAN	DAMAGE		F N		×			K		- K			100% -		- K			- %26			- 0	- K	- K		100% -	
TET TAN			Σ		1					1			100%		1			100%			35%	1	-		20%	
ATED SOV		PERFS	(ЕАСН)		3			9		80			7		7			4			1	9	3		2	
VS SIMUL	GUN EFFECTS	IMPACTS	(EACH)		32			92		30			32		34			59			12	14	25		33	
UN ATTACK			(EACH)	96	68	115	79	69	0/	80	103	79	52	165	96	103	75	83	61	58	117	89	43	129	95	74
ANGLE G	A-10 ATTACK ^{††}	DIVE	ANGLE (°)	6.9	10.6	6.5	4.4	6.6	5.3	8.3	10.4	6.5	5.8	5.6	9.6	10.9	5.4	10.1	9.7	10.0	5.8	4.4	4.2	5.4	7.4	7.9
AIRCRAFT IN LOW ANGLE GUN ATTACK VS SIMULATED SOVIET TANK COMPANY		OPEN	RANGE (FT)	2682	2000**	4523	3329	2710	2186	3448	3683	2619	2024	3178	2099	2870	2373	2434	2253	2152	4055	2296	777	2795	3087	2401
-10 AIRCE	PROACH	ALT	(FT)	290	355	1	1	370	180	1	1	ı	200	1	ı		165	395	290	315	1	1	1	250	1	340
TWO A-10	A-10 APPROACH	SPEED	(FPS)	540	521	509	554	551	578	246	527	527	557	527	518	667	538	536	548	547	509	546	523	530	527	543
		TARGET		9	9	9	5	5	16	16	16	12	12	11	11	2	2	2	2	2	7	14	1.5	7	7	4
	A-10 [†]	PASS	NO.	P1-3	P1-6	P2-11	P2-2	P1-8	P1-1	P2-8	P2-10	P2-6	P1-7	P2-4	P2-7	P2-5	P1-5	P1-9	P1-10	P1-11	P2-3	P1-2	P2-1	P1-4	P2-9	P1-12

AVERAGES

++
OPEN FIRE SPEED, ALTITUDE,
NOTES: +A-10 FIRED AT TARGET NOTED; RDS MAY HAVE IMPACTED ADDITIONAL TARGETS. +*RANGE.

**RANGE. 6 TANKS K-KILLED 8 TANKS IMMOBILIZED 35 98 7.1 2759 286 TOTALS OR 535 AVERAGES 23

COMBAT DAMAGE ASSESSMENT TEAM

A-10/GAU-8 LOW ANGLE FIRINGS
versus

SIMULATED SOVIET TANK COMPANY
(15 June 1978)

REPORT

DR. R.H.S. STOLFI, Naval Postgraduate School

DR. J. E. CLEMENS, Battelle Columbus

MR. R.R. McEACHIN, Battelle Columbus

REPORT

I. Background

Since February 1978, the Armament Directorate, A-10

System Program Office, Wright Patterson Air Force Base, Ohio, has conducted firing tests using the A-10/GAU-8 system in low level, air-to-ground engagements of armored targets. The tests have been conducted within the framework of the GAU-8 30mm ammunition Lot Acceptance Verification Program (LAVP)-Airborne. The LAVP has the following objectives which apply to the present tests:

- A. To evaluate the performance of existing production lots of GAU-8 ammunition when fired from the air under operational conditions.
- B. To evaluate the lethality of GAU-8 ammunition against armored targets when fired at low level from A-10 aircraft using operational tactics.

To conduct the LAVP program, the Armament Directorate has cooperated with Headquarters, Tactical Air Command, Langley AFB, Virginia and in turn with the Tactical Fighter Weapons Center, Nellis AFB, Nevada. Within the framework of that cooperation, the Armament Directorate has set up a Combat Damage Assessment Team (CDAT) to plan and execute the firing tests and evaluate the results. The CDAT functions under the direction of a Combat Damage Assessment Committee (CDAC) which has prepared this report of the firing test of 15 June 79.

II. Test Philosophy

To generate realistic data, the CDAC determined to use a highly empirical technique of destructive testing of actual target tanks. Tests have involved firings at individual tanks in November 1977 and February - March 1978, and more recently, arrays of vehicles in tactical formations. The experimental setup for the firings of 15 June 78 involved the second use of a multitarget, tactically arrayed tank formation for attack by the A-10/GAU-8 system. The CDAC elected to simulate a Soviet tank company as organized within a tank division as the target array for two attacking A-10 aircraft. As few constraints as possible were placed on the attacking pilots in an attempt to develop as much realism as possible. Figure 1 shows the test factors which would have been ideal in the test of 15 June 78 and the practicable setup which was achieved.

III. The Simulated Ground Combat Situation

The firing test of 15 June 78 simulated the attack by two A-10 aircraft on a Soviet tank company. The CDAC hypothesized the Soviet tank company to be the lead march security detachment for the battalion, which in turn, is the advance guard of a larger mobile formation. The lead detachment is operating approximately five kilometers in front of the Soviet battalion column. The mission of the advance company is to ensure the uninterrupted advance of the battalion and provide security against attack. Upon meeting heavy resistance, the company

FIGURE 1.

Empirical Test Philosophy

Comparison of Ideal & Practicable Test Situations

	Ideal	Practicable
	Test Parameters	Test Parameters
	THE RESERVE OF THE AMERICAN	
1.	Air Attack Realism 1.	Air Attack Realism
	a. Actual A-10/GAU-8	a. Actual A-10/GAU-8
	b. 30mm APIT	b. 30mm APIT
	c. European Weather &	c. Nevada desert terrain
	Terrain	and Weather
	d. Optimum open fire	d. Long open fire ranges
	ranges (2000 feet)	(4000-3000 ft safety constraints)
	e. Low altitude attack	e. Low altitude attack
	(<5° Dive Angle)	(< 5° Dive Angle)
	There's words are a discontinuous	, to be any in
2.	Air Defense Realism 2.	Air Defense Realism
	a. Automatic cannon firing	a. Low altitude, low angle,
	at A/C	minimum exposure attacks
		vs assumed AD system
	<pre>b. Missile systems firing at A/C</pre>	b. Ditto
	c. Small arms firing at A/C	c. Ditto
	d. AD suppression by A/C	d. No suppression simulation
	a, in supplemental in the	in test
2	Mhyont Maygota and Dogtying 2	Mhwaat Maurata and Doctuins
٥.	Threat Targets and Doctrine 3.	Threat Targets and Doctrine
	a. T62/T64/T72 high fidelity-	a. Simulated Soviet Tanks
	targets	a, bimilated bovice lamb
	b. Stowed combat loads	b. Stowed combat loads
	(in T-62/T-64/T72)	(in US M-47)
	c. Realistic crew station	c. Wooden crew mannikins
	postures	
	d. Dynamic combat formation	d. Static combat formation
	e. Maneuvering evasive	e. Stationary targets
	targets	

deploys into an appropriate combat formation to reduce the resistance or form a base of fire for offensive action by the remainder of the battalion.

A Soviet tank company, which is operating as simulated in the firing test, would probably have other units attached to it for its support. Attached units might include any one or all of the following elements: (1) motorized rifle platoon, (2) engineer detachment, (3) chemical defense element. The lead attachment simulated in the firing test consisted of tanks alone. The pure tank formation was arranged with two platoons up and one back simulating an assault posture. The tanks used in the firing test were US M-47 tanks. The tanks were not maneuvered during the firing test and the formation was essentially a "snapshot" of the company at a single point in time (See Figure 2).

IV. The Target Tanks

The US M-47 tank was the most effective target available in sufficient numbers to simulate Soviet T-55 and T-62 tanks. The US tank is similar in armor protection to the Soviet tanks, and with the appropriate purging of its gasoline fuel system a similar target from the viewpoint of stowed fuel. The most significant difference in survivability among the vehicles is the superior protection of the M-47 tank at the rear of the turret attributable to the extreme overhang and attached stowage box.*

The Soviet T-64 tanks are ill-understood from the viewpoints of

^{*} See Sketch 1.





Figure 2. -- THE TANK TARGET ARRAY



DISCUSSION: The US M-47 tank was designed with a large overhang at the rear of the turret and attached heavy gauge steel stowage box. The combination of box, overhang, and components within the overhang of the turret drastically reduces chances of (1) projectiles perforating the rear of the turret, and (2) perforating projectiles causing casualties or impacting stowed ammunition in the fighting compartment. Soviet T-55 and T-62 tanks do not have overhanging turrets and are significantly more vulnerable to impacts at the rear of the turret and resulting catastrophic kills from impacted stowed ammunition and fuel in the fighting compartment.

Sketch 1. -- THE US M-47 TANK: TURRET OVERHANG AND 180^O (REAR) ASPECT SURVIVABILITY armor protection and the arrangement of internal components. The decision was made, accordingly, to simulate the better known, earlier model Soviet tanks with the readily available M-47 vehicles.

The M-47 tanks used for targets were in excellent condition from the viewpoint of damage assessment. The exterior components were complete and the tanks have proven to be effective targets for the collection of exterior mobility damage. Interior components were less complete in the target tanks. All of the most essential items were present, e.g., main gun, engine, transmission, fuel tanks, ammunition racks, etc., but other items such as oil coolers, range finders, vision devices, and radios, were not present in all tanks.

The most sensitive internal items from the viewpoint of catastrophic kills and high percentage M and F kills are the following, which were placed in the test tanks as noted:

Generic Sensitive Item Test Item

- 2. Fuel-----Number 2 Diesel
- 3. Oil-----Oil in Engine, Transmission and Drive
 Components
- 4. Personnel------Articulated Plywood Mannikins

The tanks were static during the test and their engines were not running, with the result that the fuel and oil were much cooler and more inert than would have been the case with a static vehicle with its engine running. The kill ratio achieved in the firing test of 15 June 78, therefore, is probably conservative from the viewpoint of fires resulting from ignited fuel and oil.

V. The Test and Results

The test itself consisted of bringing together the ammunition, gun, aircraft, pilots, and combat arrayed and loaded tanks into a several minutes simulation of combat. In essence, the decisive elements which had been fed into the test immediately prior to the firing were the following:

- 1. Honeywell 30mm APl ammunition.
- General Electric GAU-8 Gatling gun.
- 3. Fairchild Republic A-10 attack aircraft.
- 4. USAF Fighter Pilots, 422d FWS, Nellis AFB.
- 5. US M-47 main battle tanks.

The combat simulation itself comprised the aerial fire and maneuver of the attacking A-10 aircraft. A realistic way of presenting the combat simulation is to outline the sequence of pertinent events in each firing pass. The sequence of events and pertinent data which the CDAT attempted to collect in order to reconstruct the simulated combat firing of 15 June 79 were the following:

Sequence	Event	Data
1.	Aircraft Approach	Speed, Altitude
2.	Aircraft Attack	Open Fire Range, Dive Angle
3.	Aircraft Attack	Burst Time, Rds (R) Fired
4.	Aircraft Attack	Cease Fire Range, Dive Angle
5.	Gun Effects (Accuracy)	Impacts (I) on Tanks, (I/R)
6.	Gun Effects (Lethality)	
7.	Tank Damage	Catastrophic Kills
8.	Tank Damage	Mobility (M), Firepower (F) Kills

The data noted immediately above were collected through the combined efforts of the CDAT and range personnel at Nellis AFB working together and using TSPI equipment, motion picture and

still cameras, the industrial efforts required to repair, refurbish, and field the tank targets, and various systematic research techniques used to describe weapon effects and combat damage. The most basic material used in the test - the projectile, gun, aircraft and targets - are illustrated in Figures 3 through 6. The targets were arrayed in the tactical formation of a Soviet tank company as shown in Figure 2.

The pilots making the attack worked in a two-ship, mutually supporting element and employed operational tactics throughout the test passes. The pilots approached the target area at low altitude and simulated target acquisition with the help of a forward air controller. The pilots then pressed in their attacks on the acquired targets at low altitudes and low dive angles simulating operations under the altitudes for effective acquisition and tracking by opposing air defense systems.

The A-10 maneuvering and firing during each pass at a primary target are presented in terms of basic data such as speed, dive angle, etc. in the following photographs and accompanying tables and figures. Weapon effects, various measures of effectiveness, e.g., kills per pass, other ratios, etc. and the resulting damage are noted in other paragraphs, tables, and photographs in the following section of the report.

Table II presents the test in terms of the A-10 speed during firing and is based on time, space, position information (TSPI) and the reading of heads up display (HUD) camera film. The table shows the A-10 aircraft attacking at speeds during




Figure 3. -- THE PROJECTILE: 30mm API for GAU-8 GUN

Figure 4. -- THE GUN: GAU-8 30mm GATLING



Figure 5. -- THE AIRCRAFT: USAF A-10




Figure 6. -- THE TARGET: M-47 COMBAT TANK

the firing passes varying between 578 ft/sec (342 knots) and 499 ft/sec (295 knots) and averaging overall 535 ft/sec (316 knots). The firing speeds largely in excess of 300 knots combined with the clean, unencumbered configuration of the aircraft resulted in exceptional maneuverability of the aircraft during the attacks on the tank company.

Table III presents the test in terms of the A-10 dive angles during the firing passes. The clearly configured aircraft were able to attack at low dive angles ranging between 4.4 and 10.8 degrees. The low dive angles resulted in an overwhelming predominance of impacts against the side surfaces of the hulls and turrets of the target tanks and relatively low vertical obliquities. In the test of 15 June 78, the M-47 tanks proved vulnerable to perforation through the armored side surfaces partly because of the dive angles and resulting low vertical obliquities.

The next illustration, Table IV, shows open fire slant ranges for pass at a primary target. The attacking pilots opened fire at medium ranges for the A-10/GAU-8 system averaging 2795 feet. The actual open fire ranges clustered near the statistical average, and, as medium ranges of engagement they resulted in effective ratios of accuracy and lethality for the system.

Figure 7 is extracted from an in-flight recording of the pilots' comments during the firing. The recording shows that the pilots were faced with realistic battlefield obscuration, specifically smoke from the fires and explosions within the tanks which they had catastrophically damaged.

Figures 8 through 10 are plots of the A-10 attack path in a vertical plane against targets located at 00 in the display. The figures define the path of attack immediately before, during, and after the firing and represent an instant summary of the more important aircraft attack parameters including altitude, firing range, and dive angle (note unequal scales in feet on x and y axes).

Table V shows the burst length and number of rounds fired during each pass. For aircraft Pl, the average burst length was 1.17 seconds, which was realistically short from the viewpoint of non-maneuvering exposure to air defense fire. For the same aircraft, the average number of rounds fired was 77, which was a moderate amount, but one which promised effective numbers of impacts on targets and perforations through the armored envelope based on empirical ratios developed during testing in the LAVP. For aircraft P2, similar comments can be made.

Table VI shows the arrival mode of the projectiles which impacted the target tanks and the projectile effects in the cases where the projectiles impacted armor. The table shows that 90% of the projectiles directly impacted the target tanks while 10% arrived as ricochets off the ground. The direct impacts in turn were broken down into 53% which directly impacted the armor, and 47% which hit exterior components with varying but largely insignificant results against the armor.

Catastrophic damage to tanks largely comprises the effects of internal fires and explosions. Table VII shows the development of catastrophic damage in the tanks of the target array in terms of the observed progress of internal fires.

Tanks 11, 14, and 15, for example, were observed to burn, i.e., suffer from major internal fires and/or explosions, within 5.6 minutes of the initial firing pass.

Table VIII summarizes the damage inflicted in the firing passes and shows six tanks with catastrophic damage, three tanks with either complete or extremely high degradation of both mobility and firepower, and one tank with moderate degradation of mobility.

Table IX summarizes the distribution of perforations on the armored surfaces of the target tanks. It shows the unusual fact that 48% of the perforations were thru the turret, which comprises approximately 33% of the presented area. Partial explanation for the phenomenon is the shielding effects of the suspension components on tank hulls.

Figure 12 ties together aircraft attack parameters, weapon effects, and target damage, in effect, summarizing the entire firing test. The table shows that the pilots/planes/cannons had the skill/performance/effects to immobilize the MBTs in 38% of the firing passes and catastrophically destroy them in 26% of the passes. One of the most pressing missions of the A-10 is to blunt attacking enemy armored spearheads by physically halting (or slowing) the attacking armor. Halting enemy armor gives US Army and allied ground forces the

opportunity (1) to concentrate against deeply penetrating spearheads, and (2) to destroy more easily the immobilized or slowed enemy armor. The capability of the A-10 to halt enemy armor, thus, is at a premium, and the figure shows a particularly significant capability for immobilizing the main battle tanks used in the forcing tests to simulate a Soviet tank company in the attack.

AIRCRAFT VELOCITY (feet per second)

	(fe	et per seco	ond)		±2σ
	OPEN-	CEASE-	Pathawa and	Bullion and Countries	TOLERANCE
PASS	FIRE	FIRE	AVG	SOURCE	(feet per second)
P1-1	578	578	578.0	TSPI	12
P2-1	573	564	568.5	HUD FILM	17
P1-2	546	536	541.0	HUD FILM	17
P2-2	554	546	550.0	HUD FILM	17
P1-3	540	539	539.5	TSPI	12
P2-3	509	509	509.0	HUD FILM	17
P1-4	530	510	520.0	TSPI	12
P2-4	527	518	522.5	HUD FILM	17
P1-5	538	533	535.5	TSPI	12
P2-5	499	509	504.0	HUD FILM	17
P1-6	521	518	519.5	TSPI	12
P2-6	527	527	527.0	HUD FILM	17
	667	556	556.5	TSPI-	12
P1-7 P2-7	557 518	518	518.0	HUD FILM	17
P1-8 P2-8	551 546	552 546	551.5 546.0	TSPI HUD FILM	12 17
F2-0					
P1-9	536	531	533.5	TSPI	12
P2-9	527	536	531.5	HUD FILM	17
P1-10	548	546	547.0	TSPI	12
P2-10	527	518	522.5	HUD FILM	17
P1-11	547	550	548.5	TSPI	12
P2-11	509	509	509.0	HUD FILM	17
P1-12	543	539	541.0	TSPI	12

Table II presents the test in terms of the A-10 speed during firing and is based on time, space, position information (TSPI) and the reading of heads up display (HUD) camera film. The table shows the A-10 aircraft attacking at speeds during the firing passes varying between 578 ft/sec (342 knots) and 499 ft/sec (295 knots) and averaging overall 535 ft/sec (316 knots). The firing speeds largely in excess of 300 knots combined with the clean, unencumbered configuration of the aircraft resulted in exceptional maneuverability of the aircraft during the attacks on the tank company.

Table II. -- TEST RESULTS: AIRCRAFT ATTACK VELOCITIES

	+2-
OPEN- CEASE- PASS FIRE FIRE AVG SOURCE	±2σ TOLERANCE (°)
Pl-1 5.3 4.7 5.0 TSPI	0.5
P2-1 4.2 5.3 4.8 HUD PITCH	2.8
P1-2 4.4 4.5 4.5 HUD PITCH	2.8
P2-2 4.4 4.4 HUD PITCH	2.8
P1-3 6.9 5.7 6.3 TSPI	0.5
P2-3 5.8 5.8 HUD PITCH	2.8
P1-4 5.4 3.3 4.4 TSPI	0.5
P2-4 5.6 5.6 5.6 HUD PITCH	2.8
P1-5 5.4 3.3 4.4 TSPI	0.5
P2-5 10.9 10.7 10.8 HUD PITCH	2.8
P1-6 10.6 7.8 9.2 TSPI	0.5
P2-6 6.5 6.5 HUD PITCH	2.8
P1-7 5.8 3.6 4.7 TSPI	0.5
P2-7 5.6 4.6 5.1 HUD PITCH	2.8
P1-8 9.9 8.1 9.0 TSPI	0.5
P2-8 8.3 8.3 HUD PITCH	2.8
P1-9 10.1 7.4 8.8 T3PI	0.5
	2.8
P2-9 7.4 7.3 7.4 HUD PITCH	2.0
P1-10 7.6 5.6 6.6 TSPI	0.5
P2-10 10.4 9.5 9.9 HUD PITCH	2.8
F2=10 200 707 1102 121011	
P1-11 10.0 6.7 8.4 TSPI	0.5
P2-11 6.5 6.5 HUD PITCH	2.8
P1-12 7.9 5.9 6.9 TSPI	0.5

DIVE ANGLE (°)

Table III presents the test in terms of the A-10 dive angles during the firing passes. The clearly configured aircraft were able to attack at low dive angles ranging between 4.4 and 10.8 degrees. The low dive angles resulted in an overwhelming predominance of impacts against the side surfaces of the hulls and turrets of the target tanks and relatively low vertical obliquities. In the test of 15 June 78, the M-47 tanks proved vulnerable to perforation through the armored side surfaces partly because of the dive angles and resulting low vertical obliquities.

Table III. -- TEST RESULTS: AIRCRAFT ATTACK DIVE ANGLES

,		SLANT RANGE (feet)		±2σ
	REFERENCE	OPEN		TOLERANCE
PASS	TARGET	FIRE	SOURCE	(feet)
P1-1	16	2186	TSPI	10
P2-1	15	2264	HUD FILM	460
P1-2	14	2296	HUD FILM	460
P2-2	5	3329	HUD FILM	460
P1-3	6	2682	HUD FILM	460
P2-3	7	4055	HUD FILM	460
P1-4	4	2795	TSPI	10
P2-4	11	3178	HUD FILM	460
P1-5	2	2373	TSPI	10
P2-5	2	2870	HUD FILM	460
P1-6	6	1942	TSPI	10
P2-6	12	2619	HUD FILM	460
P1-7	12	2024	TSPI	10
P2-7	11	2099	HUD FILM	460
P1-8	5	2710	TSPI	10
P2-8	16	3448	HUD FILM	460
P1-9	2	2434	TSPI	10
P2-9	4	3087	HUD FILM	460
P1-10	2	2253	TSPI	10
P2-10	16	3683	HUD FILM	460
P1-11	2	2152	TSPI	10
P2-11	6	4523	HUD FILM	460
P1-12	4	2401	TSPI	10

Table IV shows open fire slant ranges for pass at a primary target. The attacking pilots opened fire at medium ranges for the A-10/GAU-8 system averaging 2795 feet. The actual open fire ranges clustered near the statistical average, and, as medium ranges of engagement they resulted in effective ratios of accuracy and lethality for the system.

Table IV. -- THE RESULTS: AIRCRAFT ATTACK SLANT RANGES

Pilot 2: All right.

***** (10:40:09 Pilot-1's tenth firing burst.)

Pilot 1: Up on the east. Getting smoky out here.

Pilot 1: Count 240, Bill. Good pass, Jim.

Pilot 2: 100, Bill.

Pilot 1: Got 240. Copy that, Bill.

Ground: Yeah, I got it. Thank you.

Pilot 1: (10:40:50) We are going to be unable to hit that western one the furthest to the north (3rd platoon, tank 7). There's just too much smoke obscuring it.

Ground: Okay.

Pilot 1: And I am in on that one tank I shot at last time (2nd platoon, tank 2). That beauty does not want to burn.

Ground: Roger.

***** (10:41:03 Pilot 1's eleventh firing burst.)

Pilot 2: Okay, I'm up on the last tank (1st platoon, tank 6) east of the real good smoker.

Ground: Roger.

Pilot 2: Well, I hit him.

Pilot 1: Okay, Bill, we will make one pass apiece, more. We have hit every one of the tanks.

Ground: Understand, you think you hit them all. And you are going to make one more pass.

Pilot 1: We have definitely hit them all. They're not all burning.

Ground: Okay.

Pilot 2: (10:41:43) Yeah, we're getting some fires from the easternmost (1st platoon) now.

Pilot 1: Yeah, there we go. That's what I just shot at. I will be in on the command vehicle (tank 4) this time, Billy.

Ground: Roger that.

Pilot 1: If I can find it in the middle of that smoke I'm in.

Figure 7 is extracted from an in-flight recording of the pilots' comments during the firing. The recording shows that the pilots were faced with realistic battlefield obscuration, specifically smoke from the fires and explosions within the tanks which they had catastrophically damaged.

Figure 7. -- TRANSCRIPT OF FILOTS' IN-FLIGHT VOICE RECORDING, BATTLEFIELD OBSCURATION COMMENTS




Figure 8. -- AIRCRAFT VERTICAL FLIGHT PATH, 15 JUN 79, PILOT 1, PASS 5, TARGET 2




Figure 9. -- AIRCRAFT VERTICAL FLIGHT PATH, 15 JUN 79, PILOT 1, PASS 3, TARGET 6




Figure 10. -- AIRCRAFT VERTICAL FLIGHT PATH,

15 JUN 79, PILOT 1, PASS 8, TARGET 5

A-24

		LENGTH	ROUND	S FIREI		±2σ TOLERANCE			
PASS	0	S	0			SOURCE	(rounds)		
P1-1 P2-1	1.07	0.69	70	43	**************************************	TSPI(a) HUD (b)	0.5		
P1-2 P2-2	1.04	1.00	68	64		HUD HUD	3 2		
P1-3 P2-3	1.44	1.75	96	117		HUD HUD	3 2		
P1-4 P2-4	1.91	2.44	129	165		TSPI HUD	0.5		
P1-5 P2-5	1.14	1.54	75	103		TSPI HUD	0.5		
P1-6 P2-6	1.34	1.00	89	64		TSPI HUD	0.5		
P1-7 P2-7	0.81	1.46	52	96		TSPI HUD	0.5		
P1-8 P2-8	1.06	1.23	69	80		TSPI HUD	0.5		
P1-9 P2-9	1.26	1.44	83	95		TSPI HUD	0.5		
P1-10 P2-10	0.94	1.56	61	103		TSPI HUD	0.5		
P1-11 P2-11	0.90	1.73	58 ·	115		TSPI HUD	0.5		
P1-12	1.13		74			TSPI	0.5		
AVERAGE	1.17	1.46	77	95	NOTES:		space, posi-		

tion information
(b) Head-up display

Table V shows the burst length and number of rounds fired during each pass. For aircraft P1, the average burst length was 1.17 seconds, which was realistically short from the viewpoint of non-maneuvering exposure to air defense fire. For the same aircraft, the average number of rounds fired was 77, which was a moderate amount, but one which promised effective numbers of impacts on targets and perforations through the armored envelope based on empirical ratios developed during testing in the LAVP. For aircraft P2, similar comments can be made.


Table V. -- THE RESULTS: AIRCRAFT ATTACK, BURST LENGTHS AND ROUNDS FIRED

TOTAL ROUNDS FIRED = 1969

	ARRIVAL	MODE		EFFECT ON ARMOR						
TARGET	GROUND RICOCHET	DIRECT	TOTAL IMPACTS	ARMOR PERFOR- ATION	ARMOR PENE- TRATION	RICOCHET OFF ARMOR				
Platoon 1			-							
. 16	6	24	30	8	9	0				
5	9	67	76	9	21	2				
6	2	30	32	3	2					
Platoon 2	1067									
2	7	52	59	4	20	3				
11	3	31	34.	7	12	1				
12	3	29	32	7	8	1				
Platoon 3										
15	1	24	25	3	5	0				
14 -	0	14	14	6	3	3 .				
7	1	11	12	1 .	3	0				
Commander	0.00									
4	3	30	33	2	8	4				
Mission Totals	35	312	347	50	100	16				

Table VI shows the arrival mode of the projectiles which impacted the target tanks and the projectile effects in the cases where the projectiles impacted armor. The table shows that 90% of the projectiles directly impacted the target tanks while 10% arrived as ricochets off the ground. The direct impacts in turn were broken down into 53% which directly impacted the armor, and 47% which hit exterior components with varying but largely insignificant results against the armor.

Table VI. -- GUN EFFECTS: IMPACT CHARACTERISTICS VS TANKS



NOTES:

(a) Time in minutes after Pass 01 (b), Company Commander

Table VII shows the development of catastrophic damage in the tanks of the target array in terms of the observed progress of internal fires. Tanks 11, 14, and 15, for example, were observed to burn, i.e., suffer from major internal fires and/or explosions, within 5.6 minutes of the initial firing pass.

Table VII. -- TANK DAMAGE: BURN TIMES FOR K-KILLS

Target Damage (a)		M	M	м		H(100Z), F(95Z)	×	H(100Z), F(100Z)		м	M	H(35X)		H(70Z), P(100Z)	
Total Perfora- tions		80	6	8		4	7	1		9	9	1		8	
Total Armor Impacts		n	32	76		27	20	76		•	ជ	•		71	
Total Target Impacts		30	92	32		59	36	32		25	14	ជ		33	wer k111
Total Rounds Fired per Platoon	989				757				228					298	11; F = Firepo
Total Passes per Tank		m	s	•			•	s						e	M - Mobility ki
Total Passes per Platoon	80				6				e						Letestrophic kill; M = Mobility kill; F = Firepower kill
Target Platoon Tank	1	16	•	9	7	7	п	11		ង	14	,	Company	4	NOTE:

Table VIII. -- TANK DAMAGE: OVERALL PICTURE; K, M, F DAMAGE

Hull Perforations	1	1	ı	1	**	1		e	7	1		1	I	10	
Engine Compartment Perforations	4	4	7	1	e	7		1.	1	1		1	i	, 16	
Turret Perforations	4	4	1	e	7	4		1	4	1		2	1	24	
Total Perforations	80	6	m	4	7	7		e	9	7		7	1	90	
Target Damage Assessment	×	×	×	M(100Z), F(95Z)	×	M(100Z), F(100Z)		×	×	M(35%)		M(70%), F(100%)		TOTAL	
Target n Target No.	16	5	9	7	п	12		15	14	7	L	4			
Platoon	1			7			e				Company Commander				

Table IX. -- TANK DAMAGE, LOCATIONS OF PERFORATIONS

(a) K - Catastrophic kill; M - Mobility kill; F - Firepower kill

NOTE:

Accuracy Related Measures*

Ratios of Impacts to Rounds Fired:

$$\frac{\text{Impacts}}{\text{Rounds fired}} = \frac{347}{1969} = 0.18 \quad \begin{array}{c} \text{(includes impacts from ricochets off ground)} \end{array}$$

$$\frac{\text{Impacts}}{\text{Rounds Fired}} = \frac{312}{1969} = 0.18 \quad \text{(includes only direct impacts)}$$

Lethality Related Measures

Ratios of Perforations to Impacts:

$$\frac{\text{Perforations}}{\text{Impacts}} = \frac{50}{347} = 0.14 \quad \text{(includes impacts from ricochets off ground)}$$

$$\frac{\text{Perforations}}{\text{Impacts}} = \frac{50}{312} = 0.16 \quad \text{(includes only direct impacts)}$$

Figure 11. A-10/GAU-8 MEASURES OF EFFEC-TIVENESS IN COMBAT SIMULATION OF 15 JUNE 78

The impacts include ricochets off ground (as noted) and also impacts on secondary and incidental targets. Accuracy, then, is firing situation accuracy and not aircraft/gun accuracy per se.

A-10/GAU-8 Versus Simulated Soviet Tank Company Ratios of Kills Per Pass (Firings of 15 June 1978)

Primary Passes	Damage Results	Ratio of Kills Per Pass
23	8 Tanks Immobilized Consisting of 6 K-Killed and 2 M-Killed Vehicles	$\frac{8}{23}$ = 0.38 Immobilizing Kills Per Pass
23	6 Tanks Catastrophically Killed	$\frac{6}{23} = 0.26$
	na da <mark>f</mark> u sika sikasa dan dab sibara.	Catastrophic Kills Per Pass

DISCUSSION:

Table X ties together aircraft attack parameters, weapon effects, and target damage, in effect, summarizing the entire firing test. The table shows that the pilots/planes/cannons had the skill/performance/effects to immobilize the MBTs in 38% of the firing passes and catastrophically destroy them in 26% of the passes.

Figure 12. A-10/GAU-8 VERSUS SIMULATED SOVIET TANK COMPANY RATIOS OF KILLS PER PASS

VI. Combat Damage Assessment

The CDAT functioned under the direction of a small Combat Damage Assessment Committee which was responsible for assessing the damage resulting from the attack, assigning kill factors, and publishing the overall report. The damage and kill assessment was based on cumulative damage from all attacks. Where possible, damage resulting from individual attacks was assessed independently as part of the overall evaluation of each target. Where the independent assessment of an individual attack is made, the assessment is presented with the caveat that when earlier attacks did not result in crew casualties or seriously degrade mobility the time between attacks provided for a significant change in posture of individual tanks on a dynamic battlefield with possible significant differences in results.

Some targets were assessed as catastrophically destroyed even though direct observation showed a delay between the attack and the burning or explosion of the vehicle. Such an assessment was made on the basis of evidence of simultaneous crew casualties which made it highly improbably that the crew would have any capability to resist the propagation of small fires into killing fires and explosions.

The assessment of weapon effects and the assignment of kill value is discussed below. Each target was examined

individually in an identical format which includes a description of the attack/passes; the number of impacts resulting in perforations, significant damage, and insignificant damage; and the rationale behind the overall assessment.

- 1. <u>Description of A-10 Attack on Tank 2</u>: Within a period of 6 minutes, tank 2 was primary target on 5 firing passes and secondary target on 2 passes.
- 2. <u>Kill Assessment</u>: M-100%, F-95%, K-O, resulting from the following impacts.
 - a. Perforations 4
- b. <u>Significant</u> <u>Impacts</u> 16 (Contribute to M or F
 kills) Damage to exterior M and F components.
- c. <u>Insignificant Impacts</u> 38 (Do not contribute to M or F kill: effective maintenance procedures require repair or replacement of damaged components.)

3. Rationale for Kill Assessment:

- a. M-100%: based on crew casualties from 4 perforations and cumulative damage to exterior mobility components especially the penetrated hub of right number 3 road wheel (Impact 42) and the driver's periscope (Impact 30) (See Figs. 15 and 16)
- b. F-95%: based on crew casualties from 4 perforations
 and cumulative damage to exterior firepower components especially
 the tank commander's and gunner's periscope heads (Impacts 11,
 (See Figs. 13 and 14).



Figure 13. -- TARGET 2, IMPACT 11




Figure 14. -- TARGET 2, IMPACT 29




Figure 15. -- TARGET 2, IMPACT 30



Figure 16. -- TARGET 2, IMPACTS 41 AND 42

- 1. Description of A-10 Attack on Tank 2: Within a period of 7.6 minutes, tank 4 was primary target on 3 firing passes.
- 2. <u>Kill Assessment</u>: 70% M-Kill and 100% F-Kill resulting from the following observed effects.
 - a. Perforations 2
- b. <u>Significant</u> <u>Impacts</u> 8, which contribute to assessment of M and F kills through resultant damage to exterior M and F components.
- c. <u>Insignificant Impacts</u> 23, which do not contribute to M and F kills. Effective maintenance procedures, however, require repair or replacement of damaged components.

3. Rationale for Kill Assessment:

- a. M-70%: based on cumulative damage to exterior mobility components especially the penetrated right number 5 road wheel hub (Impact 18) and cracked number 1 track support wheel hub (Impact 28). (See Figs. 20 and 21).
- b. F-70%: based on wounded L (Impact 5), damaged range-finder (Impact 8), and perforated gun tube (Impact 12) (See Figs. 17, 18, and 19).



Figure 17. -- TARGET 4, IMPACT 5



Figure 18 . -- TARGET 4, IMPACT 8



Figure 19. -- TARGET 4, IMPACT 12




Figure 20. -- TARGET 4, IMPACT 18



Figure 21. -- TARGET 4, IMPACTS 28 AND 29

- 1. <u>Description of A-10 Attack on Tank 5</u>: Within a period of 8.6 minutes, tank 5 was impacted as primary target on 2 firing passes and secondary target on 3 passes.
- 2. <u>Kill Assessment</u>: K-Kill, resulting from the following impacts.
 - a. Perforations 9
- b. <u>Significant and Insignificant Damage</u> resulted from 67 additional impacts, but all such damage was overridden in importance by the catastrophic internal effects of the 9 perforations.
- 3. Rationale for Kill Assessment: Every one of the 4 perforations into the turret and 5 perforations into the hull could have ignited either fuel or ammunition. By 10.3 minutes from the time it was first fired on, tank 5 was observed burning. Several minutes earlier the tank was observed smoking and the CDAT concludes that a fuel (or oil) fire was ignited and rapidly developed into catastrophic explosions of stowed ammunition and ignition of fuel in main cells. The crew casualties assessed from perforations 5, 6, 8, and 11 would have prevented the crew from controlling any internal fire. (See Figures 22, 23, 24 and 25.)



Figure 22 . -- TARGET 5, INTERIOR VIEW OF IMPACTS 5 AND 6




Figure 23. -- TARGET 5, IMPACT 8




Figure 24. -- TARGET 5, IMPACT 11



Figure 25. -- TARGET 5, INTERIOR VIEW OF IMPACT 11

- 1. <u>Description of A-10 Attack on Tank 6</u>: Within a period of 8.4 minutes, tank 6 was impacted as primary target on 3 firing passes, secondary target on 2 passes, and incidental target on 1.
- 2. <u>Kill Assessment</u>: K-Kill resulting from the following observed effects.
 - a. Perforations 3
- b. <u>Significant</u> and <u>Insignificant</u> <u>Damage</u> resulted from 29 additional impacts. All such damage, however, was overridden in importance by the catastrophic internal effects of the 3 perforations.
- 3. Rationale for Kill Assessment: Two perforations (10 and 33, see Figs. 27, 28) were achieved into the engine compartment and both were capable of igniting fuel or oil in that area. One additional perforation (3, see Fig. 26) through the TC's cupola had the capability of killing or wounding the three crew members in the turnet and igniting their clothing. The tank was observed to be smoking 3.2 minutes after it had been fired upon and the CDAT made the assessment that a fuel or oil fire was propagated by the combined effects of perforations 3, 10, and 33, which caused the fire and prevented the crew from controlling it.



Figure 26. -- TARGET 6, IMPACT 3




Figure 27. -- TARGET 6, IMPACT 10




Figure 28 · -- TARGET 6, IMPACT 33

- Description of A-10 Attack on Tank 7: The target tank
 was impacted as primary target on 1 firing pass from the right
 side.
- 2. <u>Kill Assessment</u>: 35% M-Kill resulting from the following impacts.
 - a. Perforations 1
- b. <u>Significant</u> <u>and</u> <u>Insignificant</u> <u>Damage</u> resulting from
 11 additional impacts.
- 3. Rationale for Kill Assessment: One perforation was achieved into the transmission compartment (impact 1, see Fig. 29).

 Although the transmission was not damaged, the impact damaged the right drive sprocket. Six additional hits (non-perforating impacts) were scored (impacts 3, 5, 6, 9, 10, and 11), which significantly damaged the track, road wheels, and track support rollers of the target tank. The partial mobility kill was assessed on the basis of the cumulative damage resulting from impact 1 and also especially impacts 9 and 10 (see Figs. 30 and 31).



Figure 29 . -- TARGET 7, IMPACT 1




Figure 30. -- TARGET 7, IMPACT 9



Figure 31 . -- TARGET 7, IMPACT 10

- 1. <u>Description of A-10 Attack on Tank 11</u>: Within a period of 4.4. minutes, tank 11 was impacted as primary target on 2 firing passes, secondary target on 1 pass, and incidental target on 2 passes all from the right side.
- 2. <u>Kill Assessment</u>: K-Kill resulting from the following observed effects.
 - a. Perforations 7
- b. <u>Significant and Insignificant Damage</u> resulting from 27 additional impacts. All such damage, however, was overridden in importance by the catastrophic internal effects of the 7 perforations.
- 3. Rationale for Kill Assessment: Three perforations (3, 4, and 27; see Figs. 32, 33, and 38) were achieved into the fighting compartment, two of which had the capability of causing crew casualties and/or igniting stowed ammunition.

 Four perforations (12, 13, 18, and 23; see Figs. 34, 35, 36, and 37) were achieved into the engine compartment, one of which penetrated into the right fuel tank. The CDAT assessed an immediate K-Kill resulting largely from perforation 23 through the right fuel tank, which in combination with the casualty-producing perforations (impacts 3 and 4), other perforations, and external impacts resulted in an uncontrollable fuel fire.




Figure 32. -- TARGET 11, IMPACT 3



Figure 33 . -- TARGET 11, INTERIOR VIEW OF IMPACT 4




Figure 34 . -- TARGET 11, IMPACT 12



Figure 35. -- TARGET 11, IMPACT 13



Figure 36. -- TARGET 11, IMPACT 18



Figure 37. — TARGET 11, IMPACT 23




Figure 38. -- TARGET 11, IMPACT 27

- 1. Description of A-10 Attack on Tank 12: Within a period of 2.6 minutes, tank 12 was impacted as primary target on 2 passes, secondary target on 1 pass, and incidental target on 2 passes all from the right side.
- 2. <u>Kill Assessment</u>: 100% M-Kill and 100% F-Kill resulting from the following observed effects.
 - a. Perforations 7
- b. <u>Significant Impacts</u> 10, which contribute to assessment of M and F kill through resultant damage to exterior M and F components.
- c. <u>Insignificant Impacts</u> 15, which do not contribute to M and F kill. Effective maintenance procedures, however, require repair or replacement of damaged component.

3. Rationale for Kill Assessment:

- a. M-100% based on perforations 5, 6, 7 and 27, which killed or wounded all five crew members, perforation 15, which damaged engine and transmission, and eight additional impacts, especially numbers 17, 19, and 22, which significantly damaged exterior mobility components.
- b. F-100%: based on perforations 5, 6, 7, and 27, which killed or wounded all five crew members, and impacts 20 and 23, which jammed the turret making it impossible to traverse.
- c. See Figs. 39,40 and 41 for photographs illustrating the weapon effects and damage from impacts 7 (gunner casualty), 17 (road wheel hub penetrated), and 20 (turret jammed).




Figure 39. -- TARGET 12, IMPACT 7



Figure 40. -- TARGET 12, IMPACT 17



Figure 41 . -- TARGET 12, IMPACT 20

Tank Target Damage Summary M-47 Tank Number 14

- 1. <u>Description of A-10 Attack on Tank 14</u>: Within a period of 0.9 minutes, tank 14 was impacted as primary target on 1 firing pass and secondary target on 1 additional pass from the right front and right side respectively. The tank was observed to explode internally during the primary pass from the right front.
- 2. <u>Kill Assessment</u>: K-Kill resulting from the following observed effects.
 - a. Perforations 6
- b. <u>Significant and Insignificant Damage</u> resulting from
 8 additional impacts. All such damage, however, was overridden
 in importance by the catastrophic effects of the 6 perforations.
- 3. Rationale for Kill Assessment: The CDAT assessed the damage to tank 14 as an immediate catastrophic kill based on the observed internal ammunition explosion during the first firing pass against it. Perforation number 13, which had the location, azimuth, and residual energy to contact and (ignite) stowed ammunition was the killing agent (see Figs. 42, 43).



Figure 42. -- TARGET 14, IMPACT 13



Figure 43. -- TARGET 14, INTERIOR VIEW OF IMPACT 13

Tank Target Damage Summary M-47 Tank Number 15

- 1. <u>Description of A-10 Attack on Tank 15</u>: This tank was impacted as primary target on 1 firing pass. During the pass, the attacking pilot fired 43 rounds in a 0.69-second burst with 25 impacts on target.
- 2. <u>Kill Assessment</u>: K-Kill resulting from the following observed effects.
 - a. Perforations 3
- b. <u>Significant and Insignificant Damage</u> resulting from 22 additional impacts. All such damage, however, was over-ridden in importance by the catastrophic effects of the 3 perforations.
- 3. Rationale for Kill Assessment: Two projectiles (impacts 2, and 3) perforated the hull armor and penetrated into the right fuel tank. One additional projectile (impact 11) perforated the hull armor at the right front of the fighting compartment with high probability of resultant fragment/spall wounds to one crew member (bow gunner). The tank was observed to be burning intensely approximately 2.5 minutes after the firing pass. The CDAT assessed a K-Kill resulting from the rapid propagation of a major fuel fire which could not be controlled by the unwounded crew members (see Fig. 44 for impacts 2, 3 into fuel tank).




Figure 44. -- TARGET 15, IMPACTS 2 AND 3

Tank Target Damage Summary M-47 Tank Number 16

- 1. <u>Description of A-10 Attack on Tank 16</u>: Within a period 8.6 minutes, tank 16 was impacted as primary target on 3 firing passes all from the right side.
- 2. <u>Kill Assessment</u>: K-Kill resulting from the following observed effects.
 - a. Perforations 8
- b. <u>Significant</u> <u>and</u> <u>Insignificant</u> <u>Damage</u> resulting from 22 additional impacts. All such damage, however, was over-ridden in importance by the catastrophic effects of the 8 perforations.
- 3. Rationale for Kill Assessment: Four projectiles (impacts 8, 10, 12, 13) perforated the right side of the turret with high probability of causing casualties to tank commander, gunner, and loader. Four projectiles (impacts 5, 7, 18, 20) perforated the engine compartment armor with indeterminate damage but probable ignition of fuel and/or oil in that area. The target began to smoke immediately after the second firing pass against it, and 2.6 minutes later, shortly after the third firing pass, was observed to be burning. The CDAT assessed a K-Kill resulting from the rapid propagation of a fuel fire during and after the second firing pass, which could not be controlled by the crew (see Figs. 45, 46, 47, 48, 49, 50 for impacts 8, 12, 18 and 20, as representative perforations of turret and engine compartment).



Figure 45. -- TARGET 16, IMPACT 8




Figure 46. -- TARGET to, INTERIOR VIEW OF IMPACT 8




Figure 47 . -- TARGET 16, IMPACT 12




Figure 48 . -- TARGET 16, INTERIOR VIEW OF IMPACT 12



Figure 49. -- TARGET 16, IMPACTS 17 AND 18




Figure 50 . -- TARGET 16, IMPACTS 17, 18, 19, 20, 21, 22, 23, AND 24

Summary and Conclusions VII.

On 15 June 1978, at Nellis AFB, Nevada, the Combat Damage Assessment Team (CDAT) conducted firings of the A-10/GAU-8 weapon system against an array of 10 tanks simulating a Soviet tank company deployed for an attack. The purpose of the firing test was to evaluate the effects of the 30mm API antitank ammunition of the GAU-8 gun under challenging conditions of engagement for the A-10/GAU-8 system against realistically simulated Soviet tank formations. The CDAT used M-47 tanks stowed with main gun ammunition, diesel fuel, lubricating oil, and crew mannikins to simulate the Soviet tanks. The pilots of the two A-10 aircraft used in the firings conducted their attacks at low altitudes and low dive angles which simulated attack below the altitude of effective engagement for opposing air defense systems using acquisition and fire control radar.

The firing test can be summarized in terms of the following data which were collected and/or extracted from the firings:

Aircraft Parameters

- Speed (average) - - - 316 knots 1.
- Dive Angle (average) - - 7.1° 2.
- Open Fire Slant Range (average) - 2759 ft
- 4. Burst Length/Rounds (averages) - - - 1.3 sec/86 rds
- 5. Number Passes (primary) - - - - - 23
- Target Aspects (predominantly) - Right Side 6.

Weapon Effects Target Damage

- Rounds Fired - - 1969 1. 1. K-Kills- - - 6
- Impacts- - - 347 2. Hi% M+F Kills- 3 2.
- Ricochets (off grnd) -3. 35
- 3. M Kill - - 1 4. F Kill - 0 Direct Hit (non-perf)-4. 262
- 5. Negligible - 0 Perforation- - - - 50

These data and the more detailed base from which they were extracted can be arranged into measures of effectiveness for the A-10/GAU-8 system under conditions similar to those in the firing test, i.e., empirical combat simulation. The following values of effectiveness are based on the firing test on 15 June 1978 and can be expected to be similar in future empirical simulations of combat:

Measures of Effectiveness

Accuracy Related Ratio:	Lethality Related Ratio:
Direct Impacts Rounds Fired = 0.16	$\frac{\text{Perforations}}{\text{Direct Impacts}} = 0.16$
Weapon System Effectiveness Ratio:	Weapon System Effectiveness Ratio:
Tank Immobilized = 0.39	$\frac{\text{Tanks K-Killed}}{\text{Passes}} = 0.26$

The ten target tanks were attacked predominately from the right side and suffered the severe damage shown in Figure 1 and Table VIII. Seven of the tanks, however, were impacted more than once as primary targets, and all of the tanks were also secondary and/or incidental targets during passes directed primarily against neighboring tanks. The large number of primary passes and accompanying secondary and incidental impacts help to explain the severe damage to the tank and contrasting moderate ratios of damage and kills per pass.

The data and measures summarized above, and the other data contained in this report, support several conclusions:

The A-10/GAU-8 system in realistic simulation of

combat is capable of inflicting K, M and F Kills on M-47 and similarly protected main battle tanks, e.g., Soviet T-55 and T-62 tanks.

- 2. The system in low level attacks can perforate specifically the side and rear surfaces of the hulls and turrets of M-47 and similarly protected main battle tanks.
- 3. The system is an effective killing agent against the side and rear surfaces of M-47 and similar tanks when firing moderate length bursts of $1.0-1.5 \, \sec/65-100 \, \mathrm{rds}$.

INITIAL DISTRIBUTION LIST

		No.	Copies
1.	Defense Documentation Center Cameron Station Alexandria, VA. 22314		2
2.	Library, Code 0212 Naval Postgraduate School Monterey, CA. 93940		2
3.	Department Chairman Department of National Security Affairs Naval Postgraduate School Monterey, CA. 93940		2
4.	Professor R.H.S. Stolfi Department of National Security Affairs Naval Postgraduate School Monterey, CA. 93940		15
5.	CAPT L. O. Ratley III, USAF ASD/YXA Wright Patterson AFB, OH 45433		20
6.	MAJ Charles Earnhart AFIT/CIP Wright-Patterson AFB, OH. 45433		2
7.	COL James C. Keenan AFIS/INH Ft. Belvoir, VA. 22060		1
8.	BRIG GEN William D. Curry 355 TFW/CC Davis Monthan AFB, AZ. 85707		1
9.	COL Wayne E. Davis 1411 Gemini Circle Moody AFB Valdosta CA 31601		1

10.	COL Robert Dilger ASD/YXA Wright-Patterson AFB, OH. 45433	20
11.	COL W. S. Harpe AFMPC/DPMY Randolph AFB, TX. 78148	1
12.	BRIG GEN James R. Hildreth ACWAL/AIMVAL JTDD Nellis AFB, NV. 89191	1
13.	COL J. McFadden 354 TFW/DCM Myrtle Beach AFB, SC. 29577	1
14.	Mr. C. E. Meyers Department of Defense Office of Defense Research and Engineering The Pentagon Washington, D.C. 20301	1
15.	BRIG GEN T. H. McMullen TAC/DR Langley, AFB, VA. 23665	1
16.	DEAN OF RESEARCH Naval Postgraduate School Monterey, CA 93940	2
17.	General Elwood Quesada (Retd.) L'Enfant Plaza Washington, D. C. 20024	1
18.	Mr. P. M. Sprey Box 264, R.D. 1 Glenn Dale, MD. 20769	1
19.	Mr. Thomas Turner Fairchild Industries Germantown, MD. 20767	2
20.	Industrial College of the Armed Forces Library Ft. Lesley J. McNair Hashington D. C. 20210	1

21.	Mr. Bernard Kornhauser System Planning Corp. 1500 Wilson Blvd. Suite 1500 Arlington, VA. 22209	1
22.	MAJ G. H. Felix, USAF Marine Corps Command & Staff College Quantico, VA. 22134	1
23.	USMC Development & Education Cmd Quantico, VA. 22134	3
24.	USAF TAWC Eglin AFB, FL. 32542	5
25.	HQ USMC Deputy Chief of Staff Requirements MAJ GEN P. X. Kelley Arlington, VA. 22212	5
26.	USAF Air University Library Maxwell AFB, AL. 36112	1
27.	CMDR, Naval Weapons Center China Lake, CA. 93555 ATTN: Mr. Bates	2
28.	Commander (COL R. Gomez) Ballistic Research Laboratory Aberdeen Proving Ground, MD. 21005	5
29.	GE, Armament Systems Dept. Director Lakeside Ave. Burlington, VT. 05401	1
30.	HQ TAC/DO Langley AFB, VA. 23665	1
31.	354 TFW/DO Myrtle Beach AFB, SC. 29577	2
32.	23 TFW/DO England AFR IA 71301	2

33.	USAC 4SC Ft. Leavenworth, Kansas 66027	1
34.	355 TFW/DOW Davis Monthan AFB, AZ. 85707	1
35.	355 TFW/DO(A-7) Davis Monthan AFB, AZ. 85707	1
36.	355 TFW/DO(A-10) Davis Monthan AFB, AZ. 85707	3
37.	333 TFTS/CC Davis Monthan AFB, AZ. 85707	1
38.	333 TFTS/DO Davis Monthan AFB, AZ. 85707	1
39.	333 TFTS/WPNS (CAPT Haar) Davis Monthan AFB, AZ. 85707	2
40.	AFTEC A-10 Test Force/CC Davis Monthan AFB, AZ. 85707	1
41.	OLAC 4444 OPS SQ (ISD) Davis Monthan AFB, AZ. 85707	1
42.	355 TTS/CC Davis Monthan AFB, AZ. 85707	1
43.	Mr. Bob Forker Hughes Helicopters Ordnance Division Culver City, CA. 90230	1
44.	Herrn Dr. Granier Bundesarchiv-Militärarchiv 78 Freiburg im Breisgau Wiesentr 10 West Germany	1
45.	Herrn Dr. Horst Boog Wiss Oberrat Militärgeschichtliches Forschungsamt 7800 Freiburg im Breisgau West Germany	2

46.	LT COL Robert G. Appelbaugh USAF TAWC/TEFE Eglin AFB, FL. 32542	1
47.	Albert F. Simpson Historical Research Center Maxwell AFB, AL. 36112	2
48.	CMDR Naval Air Systems Command ATTN: PMA 235 B Washington, D. C. 20361	1
49.	CMDR McMichael DASD/ISA/ED Rm 4D800 The Pentagon Washington, D. C. 20301	1
50.	LT COL Howard J. Pierson 180 Magnolia Shaw AFB, SC. 29152	1
51.	USAF DCS/Plans & Operations Directorate of Operations Tactical Division BF939B The Pentagon Washington, D. C. 20301	2
52.	USAF DCS/Programs & Resources Director of Programs Tactical Branch 4C152 The Pentagon Washington, D. C. 20301	2
53.	USAF DCS/Research & Development Directorate of Operational Requirements & Development Plans Tactical Division 5E381 The Pentagon Washington, D. C. 20301	2

54.	HQ TAC/DO AT Langley AFB, VA. 23665	1
55.	HQ TAC/DO O Langley AFB, VA. 23665	2
56.	HQ TAC/DOOO Langley AFB, VA. 23665	2
57.	HQ TAC/DOOF Langley AFB, VA. 23665	1
58.	HQ TAC/XP Langley AFB, VA. 23665	1
59.	USAF Academy Library USAF Academy, Colo. 80840	2
60.	USAF TFWC/TA Nellis AFB, NV. 89191	1
61.	57 FWW/DO Nellis AFB, NV. 89191	1
62.	12 AF/DO Bergstrom AFB, TX. 78743	2
63.	9 AF/DO Shaw AFB, SC. 29152	2
64.	CINCUSAFE/DO Ramstein AFB APO 09012	1
65.	CINCUSAFE/DOOF Ramstein AFB APO 09012	2
66.	CINCUSAFE/DOOT Ramstein AFB APO 09012	2
67.	CINCUSAFE/DOST Ramstein AFB APO 09012	2